#### 1288

# 6<sup>th</sup> October 1937

# $PROCEEDINGS\ of\ INQUEST$

held upon the body of

Donald Neil McDonald

at Geelong

Received at the Crown Law Offices

8 OCT 1937

P.M.

J.G.H. Ritchie

Deputy Coroner.

In witness whereof, I, the aforesaid (4) J.G.H. Ritchie JP have to this Inquisition put my hand this  $6^{th}$  day of October A.D. 1937

J.G.H. Ritchie JP

Deputy Coroner

#### PROCEEDINGS BEFORE CORONERS

## **INQUISITION**

Victoria To Wit

An INQUISITION for our Sovereign Lord King George VI, taken at Geelong in the State of Victoria, the 6<sup>th</sup> Day of October A.D. 1937 in the First year of the reign of our Lord the King, by me, J.G.H. Ritchie Esq, A Deputy Coroner Upon the view of the body of Donald Neil McDonald then and there lying dead.

Having inquired upon the part of our Lord the King when, where and How the said Donald Neil McDonald

came by his death, I say that

on the Ninth day of September 1937 at Geelong in the said State, the said Donald Neil McDonald died from Injuries accidentally received in a head-on collision with an Electric Tram whilst driving a Motor Car in Ormond Road Geelong on ninth day of September 1937.

> Signed J.G.H. Ritchie JP Deputy Coroner

Geelong East Station

Southern

Police District

9<sup>th</sup> September 1937

REPORT of 1st Const. Kuhne 7944 Relative to the death of Donald McDonald Of Queenscliff Road Moolap The Deputy ????? Mc?????/

1/ I have to report for your information that at about 6.30 ??? on 9.9.37 that an accident had occurred in Ormond Road Geelong East near the East Geelong tram terminus. I went to the scene & saw that a sedan motorcar had collided head on with a tramcar.

2/ It appears the car was being driven East & the town west. The apparently dead body of the driver was jammed in the driving seat by the front portion of the car & engine which had been driven back.

3/ The body was removed to the Geelong Hospital where it was examined by W. McLean who pronounced life extinct. It was then removed to the Morgue where it now lies awaiting your further instructions.

W.W. Kuhne 1<sup>st</sup> Const 7944

I have viewed the body of Donald Neil McDonald. Age 44 years of Queenscliff Road Moolap. Geelong Received the Report from 1st Constable W.W. Kuhue Received evidence of identification From J.F. McDonald brother of Deceased. Instructed Dr J.E. Piper to perform A Post-Mortem Examination, The Report of which I have received And read. Gave instructions and signed an Order for the burial of the body. Opened an Inquest and adjourned The same to a date to be fixed

> Signed J.G.H. Ritchie JP Deputy Coroner 13/9/37

#### CORONER'S INQUEST

\_\_\_\_

VICTORIA, TO WIT

This Deponent John Fraser McDonald
On his oath saith, I am a stock & station agent
Residing at Kaniva

I identify the body shown to me at The Geelong Hospital Mortuary on 10/9/37 as that of my brother Donald Neil McDonald of Moolap I have not seen him alive since 17/7/37

J.F. McDonald

#### CORONER'S INQUEST

\_\_\_\_

VICTORIA, TO WIT

This Deponent Lewis O'Sullivan
On his oath saith, I am the licensee of the Criterion Hotel
Residing at Geelong

At About 5.30Pm on 9.9.1937 the deceased called to see me on business

He had three small glasses of gin in the hotel
He obtained
Two bottles of beer at about 5.50Pm which
He carried out of the hotel about 5.50Pm
I walked to his
Car with him and stood talking until 6Pm.
Deceased was perfectly sober
When I left him.
I have known deceased for a number of years, and to the best
Of my knowledge was a steady driver.
Deceased had only the sight of the left eye.

L.O'Sullivan

\_\_\_\_\_

VICTORIA, TO WIT

This Deponent Herbert Deller

On his oath saith, I am a labourer Residing at Moolap

On the 9/9/37 about 6-15p.m. I was driving a horse and Cart East along Ormond Road Geelong East, going up the Hill from the Cemetery. I had no light on my cart.

A tram was coming West toward me. A

Motorcar passed me going East. This car came out on the Road to pass me, and then continued on along the crown Of the road, and run head on into the tram.

From where the car passed me to where

It collided with the tram would be a distance of approximately 30 yards. When the tram [sic] passed me it did not come back over to the left, but kept on the crown of the road.

It was just dark, and it was raining. The tram had it's lights burning and was clearly visible.

The tram car, the motorcar, that hit the tram, and my vehicle was the only traffic on the road At the time.

I could not say if the lights were on t

The car when it passed me.

I helped to get the wrecked car away

From the tram. The driver appeared to be dead.

I have read this statement over. It is

True and correct.

H.H. Deller

\_\_\_\_\_

VICTORIA, TO WIT

This Deponent Herbert Deller

On his oath saith, I am a labourer Residing at Moolap

I could see the tram approaching, it was traveling very slowly.

I could plainly hear the gong of the tram

Being sounded.

The gong sounded a number

Of times Prior to the car colliding with it.

I had

No light on my vehicle, I was well on my correct side of the road when the Motor car passed me.

No other traffic was

On the road.

I did not hear the car sound

Its horn before passing me, it may have Been sounded and I did not hear it It was wet and windy at the time.

Mr Fidge

/ The visibility was bad I never noticed whether the tail light was burning. In order to pass me the car could have passed me without going onto the tram track. He did not come back on to the road. I was about 50 or 60 yards away when I first noticed the tram. There is a hill. The tram was nearly stopped.

H.H. Deller

VICTORIA, TO WIT

This Deponent Herbert Deller

On his oath saith, I am a labourer Residing at Moolap

When the car hit it. It was traveling Slowly when I first saw the tram. The Driver f the tram had nearly stopped it when the collision Occurred. It was in motion.

Mr Dooley

The speed of the motor appeared to be 40 to 50 miles per hour

H.H. Deller

VICTORIA, TO WIT

This Deponent James Ernest Piper On his oath saith, I am a duly qualified Medical Practitioner Residing at Latrobe Terrace Geelong

On Friday September 10<sup>th</sup> 1937 I made a Post Mortem examination of the body of Donald Neil McDonald at the Geelong Hospital. There were severe and deep lacerations on the legs, body and head. Both legs were Broken and the right humerur was broken. On opening the skull no sign of fracture was Found and no severe injury to the brain Detectable. On opening the thorax it was found that several ribs were broken And one had pierced the heart that organ showed extensive calcareous pericarditia. Lungs were normal, but the liver showed sclerotic changes and the stomach smelt strongly of alcohol.

The cause of death was direct injury To the heart, combined with shock.

> J.E. Piper MD 10/9/37

VICTORIA, TO WIT

This Deponent Percival Wallis Fuller On his oath saith, I am a Motorman in the employ of the State Electricity Commission of Victoria Residing at 27 Swanson Street, Geelong

On the 9<sup>th</sup> September, 1937, I was Motorman on tramcar No.2 when It left the terminus at East Geelong at 6.19p.m. on the trip to the city and was traveling in Queenscliff Road in a westerly direction. When About a quarter of a mile from the terminus, I was casting down hill at A speed of about 15 m.p.h. when I noticed, about half a mile ahead, a motor Vehicle approaching with two bright headlights showing. The motorist Passed a horsedrawn jinker when it was some hundreds of yards away from the tram, and in doing so swung on to the centre of the track. I sounded the gong violently and applied the air brake, slowing the tram down to about 10 m.p.h. The motorist, driving erratically, appeared to make an attempt to clear the tram track, but again swung back on to the centre of the track when about 100 feet away from the tram. I immediately applied full emergency brake and had slowed down to about 3 m.p.h. I noticed the motorist was traveling at a fast speed, estimated to be from 40-50 m.p.h., and he did not slacken speed at all and came on to strike the front of the tram head on. The time was then about 6.22 p.m. The visibility was fair, with light rain falling. The tram traveled Only about 4-5 feet after the collision, and the front wheels of the tram were derailed after impact. The whole of the bonnet up to The dash board, except near side front wheel, of the motor car was crushed under the front bumper of the tram. I went to the driver's

(hand written)

Assistance, but found him unconscious, leaning against the door on the driving side. I asked Conductor Atkins to call an ambulance, which arrived shortly after, and the

Mr Fidge / The horse and cart were 30 yards

police were also notified, and took the motorist to hospital.

PW Fuller

VICTORIA, TO WIT

This Deponent Percival Wallis Fuller On his oath saith, I am a Motorman Residing at 27 Swanson Street, Geelong

Away from the tram when the Accident occurred. I saw the car Pass the cart. It passed about 60 yards from the tram. I made no measurements of distances. The motorist was traveling very fast The usual speed of a tram is 15-18 miles per hour. I was traveling at 15 mph. traveling at 15 mph under these conditions I could pull the tram up in 20 feet. I did not notice a light on Dellers [sic – the horse & cart] vehicle

Mr Dooley /

I have never measured the distance it takes to pull up a tram which is traveling at 12 to 15 mph I have never made a test

P.W. Fuller

VICTORIA, TO WIT

This Deponent Keith Martin Atkins On his oath saith, I am a Conductor in the employ of the State Electricity Commission of Victoria Residing at 26 Belfast St., Newtown Geelong

On the 9<sup>th</sup> September, 1937, I was Conductor on tramcar No.2, which had left terminus at East Geelong at 6.19p.m. on its trip to the city. When

About a quarter of a mile from the terminus in Queenscliff Road I heard the motorman ring the gong loudly and felt the emergency brakes being applied. I was

Standing at the rear entrance to the saloon, and I looked through the front window and saw the headlights of an approaching motor

Car in the centre of the tram track a short distance away. I

Then felt the full emergency brake being applied, and the tram slowed down, but the motor car came on to strike the tram head on.

The impact threw me to the other end of the saloon. I went to the motorist's assistance and asked Mr. Deller to call an ambulance, which arrived shortly afterwards.

Keith M Atkins

VICTORIA, TO WIT

This Deponent William Walter Kuhne On his oath saith, I am a Ist Constable of Police Residing at Geelong East

At about 6-30.p.m. on 9/9/37 as a result of information Received, I went to the scene of an accident in Ormond Road Geelong East at a spot about 300-400 yards west of the East Geelong tram terminus.

I there saw that a motorcar had collid-

ed head on with a tramcar. The driver of the car who was the deceased Donald Neil McDonald was seated in the driving seat

and was jammed in by the front portion of the car which had been forced back by the impace. The deceased appeared then to be dead

I had the body conveyed to the Geelong

Hospital by Civil Ambulance. Dr McLean made an examination of The deceased and stated that life was extinct.

I then removed the body to the Geelong

Hospital Mortuary.

I later stepped the width of the road and various

other distances.

The full width of the road from fence

To fence was 33 paces. From the fence to the edge of the gravel On the North side of the road was 8 paces, from edge of gravel

To bitumen 3 paces, from edge of bitumen to North tram rail 4 paces, 2 paces between tram rails, south tram rail to edge

of bitumen 5 paces, from bitumen to edge of gravel (south) 5 paces, from edge of gravel to fence 6 paces.

The collision occurred in wet circumstances

With light conditions very bad.

The car was completely wrecked and the tram

damaged and derailed.

W.W. Kuhne 1st Const 7944

# PUBLIC RECORDS OFFICE VICTORIA

UNIT 1339 VPRS 24/P FILE 1937/1288

Accessed by Donald's youngest daughter Heather and youngest Granddaughter Janet Nov 2005